STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155115	A. BUILDING 01 B. WING _____	R 01/02/2013

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
CARDINAL NURSING AND REHABILITATION CENTER	1121 E LASALLE AVE SOUTH BEND, IN 46617

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
{K 000}	INITIAL COMMENTS	{K 000}		

A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey Conducted on 11/21/12 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).

Survey Date: 01/02/13

Facility Number: 000048
Provider Number: 155115
AIM Number: 100275330

Surveyors: Joe L. Brown, Jr., Life Safety Code Specialist, & Robert Sutton, Life Safety Code Specialist Trainee.

At this PSR survey, Cardinal Nursing and Rehabilitation Center was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety From Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.

This three story facility with a basement was determined to be of Type II (111) construction with a one story addition determined to be of Type V (111) construction and both were fully sprinklered. The facility has a fire alarm system with smoke detection on all levels including the corridors, areas open to the corridors, and battery operated smoke detectors in the resident sleeping rooms. The facility has a capacity of 144 with a census of 109 at the time of this survey.

All areas where the residents have customary

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE | TITLE | (X6) DATE

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155115	A. BUILDING 01 B. WING _____	R 01/02/2013

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
CARDINAL NURSING AND REHABILITATION CENTER	1121 E LASALLE AVE SOUTH BEND, IN 46617

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
{K 000}	Continued From page 1 access were sprinklered. All areas providing facility services were sprinklered. Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 01/07/13.	{K 000}		